



Tech Info Library

Apple Coax/Twinax Card: Rev B Fixes MacDFT & Video Problems

Article Created: March 9, 1991

Article Reviewed Only:

Article Last Updated:

TOPIC -----

What does the "new" Apple Coax/Twinax card revision do? Who needs it?

DISCUSSION -----

The new Apple Coax/Twinax card offers no new functionality, but it does resolve a somewhat rare incompatibility problem with the Macintosh Display Card 8•24 and Macintosh Display Card 8•24 GC. The only difference between this "new" card and the "old" one is that the inductor/ferrite bead replaces a jumper wire, and the masking on the board says that the board is revision "B."

You should consider upgrading to the new cards if you have the following problem:

MacDFT hangs on boot when the initial "splash screen" appears. MacDFT hangs before the Window Manager completes drawing the window frame, or shortly after the frame draw and the content region goes black. This problem happens often on systems with 8•24 style video and Coax/Twinax cards. It is also more likely to happen on a Macintosh IIci, Macintosh IICx, or Macintosh IIfx than on a Macintosh II or Macintosh IIX.

But a similar problem has a different solution: Some NuBus conflicts happen with the Portrait or Workstation display cards and the Apple Coax/Twinax card. The error shows up when launching MacDFT. At launch, the Macintosh bombs and gives a bus error (if the system has MacsBug installed) or displays a system error of ID=28. Use A/ROSE v1.1.2 to fix this problem. Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7181