



# Tech Info Library

## Apple IIC Prob/Cure: Data Errors When Sending to Serial Device

This article last reviewed: 10 March 1988

PROBLEM DESCRIPTION: Data errors occur when the Apple IIC transmits data to a serial device (modem, printer, etc.).

CAUSE: There may be a timing problem in the Apple IIC motherboard.

CURE: Check location UC7 on the motherboard for a "black" (not silver) LS161 integrated circuit. If this component is black, then this board has a timing problem so the motherboard should be replaced. Refer to the service programs binder to see if the repair can be reimbursed under a special warranty program.

If the component is silver, then the board does not have the timing problem.

If the above cure doesn't fix the problem, search on GTS and the product's name to obtain a general troubleshooting procedure.  
Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1885