



Tech Info Library

Macintosh1/2 XL(Lisa 2/5) : Clobbers Other Nodes On ATalk

Article Created: 22 April 1986

Article Last Reviewed: 17 July 1992

Article Last Updated:

PROBLEM DESCRIPTION: A Macintosh 1/2 XL (originally called Lisa 2/5) may suffer from noise problems on its receiving lines. This interferes with its ability to hear other network devices, so may think it is safe to broadcast even if another node is transmitting. This can result in collisions that clobber other node's transmissions. The problem only happens with units that have the old I/O PCBs (the ones with battery packs).

CAUSE: The old I/O PCB needs to be upgraded.

CURE: 1. Cut R38 (location 12E above the battery pack).
2. Cut the trace leading to pin 3 of RP4 (location 12F)

If the above cure doesn't fix the problem, refer to the Lisa Tech Procedures to obtain a troubleshooting procedure.

Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1897