



# Tech Info Library

## Macintosh: 512K With 800K Disk Drive

Article Created: 22 April 1986

Article Last Reviewed: 17 July 1992

Article Last Updated: 17 July 1992

BACKGROUND: A 512K Macintosh requires a special revision of ROM to work with an 800K disk drive. Service stock PCBs commonly used as replacements when repairing Macintoshes do not have the 800K upgraded ROM installed.

IMPORTANT: When swapping the main logic PCB on a 512K Macintosh, perform the following:

1. CHECK FOR 800K ROM UPGRADE ON "BAD" PCB

Check the ROM installed on the malfunctioning PCB. If the ROM part numbers are 34X-0341 and 34X-0342, then they are 800K upgrade ROM and you should proceed to step 2 of this procedure. If not, then the bad PCB doesn't have 800K ROM so you don't need to worry about transferring the upgrade from the bad PCB to the new PCB.

2. SWAP 800K ROM FROM "BAD" PCB TO "NEW" PCB

If the malfunctioning PCB has the 800K ROM installed, swap them into the new PCB before installing it into the customer's Macintosh.

NOTE: If the ROM were swapped from the "BAD" PCB to the "NEW" PCB, remember to install the original ROM from the new service stock PCB into the bad PCB before returning it to Apple.

Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1900