



Tech Info Library

Super Serial Card: Blown Resistor

This article last reviewed: 28 March 1988

PROBLEM DESCRIPTION: ImageWriter causes R7 on the Super Serial Card to fail.

BEFORE YOU START: Familiarize yourself with the procedure for removal and replacement of the carriage drive transistors, referring to the ImageWriter Level I Technical Procedures.

CAUSE: One of the carriage transistors in the ImageWriter is shorted.

CURE: Follow these steps:

1. Remove the string of 4 carrier drive transistors and their associated insulators using the procedure documented in the ImageWriter Technical Procedures.
2. Check to make sure that none of the insulators is missing or cracked.
3. If any of the insulators is missing or cracked, replace them, reinstall the string of carriage transistors, and test the printer with the Super Serial Card. Otherwise, proceed to Step 4.
4. Replace the string of carriage transistors with a new set and test the printer using the Super Serial Card.
5. If the above procedure does not cure the problem, refer to Troubleshooting in the ImageWriter Technical Procedures.

Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1963