



Tech Info Library

Macintosh IIsi: Application Software Compatibility

Article Created: 15 October 1990
Article Last Reviewed: 15 July 1992
Article Last Updated:

TOPIC -----

This article summarizes the software compatibility issues at the introduction of the Macintosh IIsi.

DISCUSSION -----

The Macintosh IIsi Was Widely Seeded -----

In the United States alone, over 300 developers received Macintosh IIsi seed units. Many other developers received full documentation, and were able to test their products at Apple. This was the most extensive seeding and testing of a new computer in recent history.

Of the applications on which Apple had compatibility information, 97% either worked with the Macintosh IIsi, or were in the process of being revised. The other 3% were discontinued products.

Compatibility Issues -----

FPU: Apple identified about twenty application programs that required an FPU (and did not have an alternate non-FPU version). Many of the color paint programs that fell in this category were revised to work on all Macintosh models. However, most CAD/CAM programs and other high-end graphics/math programs still require an FPU. We will identify these applications on all compatibility lists.

Microsoft Excel: Version 2.2a or higher is recommended for all Macintosh IIsi and Macintosh LC configurations. Microsoft offers a free upgrade from 2.2 to 2.2a.

Monitor size: Several programs did not work properly on the Apple Macintosh 12-inch RGB Display, because they assumed a minimum 640-pixel by 480-pixel size. These programs were in the process of being revised.

Macintosh SE/30 cards: Some Macintosh SE/30 cards did not work with the Macintosh IIsi, due to incorrect timing and physical dimensions. All

cards that followed the guidelines in Apple's "Cards and Drivers" manual work correctly.

NuBus power requirements: Some NuBus cards exceeded the 15W power maximum specification. These cards were primarily the high-end graphics and video cards. We asked developers of these cards to include, in their manuals, references to power if they exceeded the maximum specification. We also included a caution in the Macintosh IIsi manual.

Sound: The new sound input software made it necessary for some developers to update their software. Latest versions should work with the new Macintosh models.

AppleTalk: An AppleTalk problem in System 6.0.6 was fixed in System 6.0.7, which shipped with all Macintosh IIsi and Macintosh LC systems sold in the United states.

Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6152