



Tech Info Library

Geoport and ARA 2.0 Problems (3/94)

Article Created: 28 Mar 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

We have a Centris 660AV 16 MB/230 W/GeoPort as our dial-in to network services utilizing ARA. We have regular problems with the machine in the office while attempting to answer, the answering modem would hang up during handshake, disconnecting and turning off the express modem resulting in all subsequent attempts to fail due to the modem having turned itself off.

When Using ARA, should the radio button be set to:

Express Modem
or
External Modem

Other info: Express Modem V1.1.2, GeoPort Telecom v1.0

DISCUSSION -----

The problem you're experiencing with your GeoPort is most likely caused by a recently discovered problem with the GeoPort design. A repair program has been put in place to fix the failing GeoPorts. New GeoPort pods P/N (# M3127LL/A vs. OLD # M1694LL/A) are being manufactured with the rework already implemented (detailed explanation below).

As far as the Control Panel settings, if you are using ARA and have the Express Modem Software installed you should set the control panel to "External Modem." Since ARA is "CommToolBox aware" it will allow you to select the correct device from within the ARA application. The "Express Modem" setting in the control panel is for compatibility with non-CommToolBox aware applications. Setting this either way should work from within ARA but the recommended way is to set it to "External" to allow the CommToolBox Express Modem tool to be utilized.

Detailed Description of GeoPort problem

The GeoPort pods which exhibit the problem can "buzz" during a connection attempt as well as experience problems described above.

Since the pod is not serialized, the easiest way to roll the new design into

production was to create a new part number for it. Older GeoPort pods that have had the rework can be identified by looking for a round dot marked on the label located on the bottom of the Pod. See the WWPTS Service Flash on AppleLink for more information.

The only way to determine if they have the new pods is to look for an indelible marker dot on the label located on the back of the pod. There are 2 parts to the rework, adding some washers to the ground shield and gluing the plastics to assure a tight fit. Unfortunately some of the initial pods that were reworked (and have this mark on the label) were only glued, and did not have the washer fix. This was added later and unfortunately there is no way to determine if they have the second fix. However, we shipped a very limited quantity of the units that were only glued without the washer fix. If the replacement unit has a dot on the label and the customer still has problems, the pod may need to be replaced again. The first rework should be enough to get the GeoPort working although under some conditions both reworks may be required.

Support Information Services
Copyright 1994, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14989