



Tech Info Library

Macintosh: SIMM Socket Contact Problem (11/94)

Article Created: 1 August 1991

Article Reviewed/Updated: 09 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I have had a chronic problem with my Macintosh SE/30 for about 2 years. Intermittently, when I turn on the power, it does not start up. Sometimes I get musical chimes; sometimes I don't. The fan and hard drive always power up. If I give the case a good smack, it work fine for up to a week, and then the problem recurs. If I continue using the smacking solution, the problem continues with increasing frequency. The only solution that works for any appreciable time is to remove the main logic board and reseal the SIMMs.

My technician says that the problem is due to poor quality of the SIMM sockets on the main logic board.

Can I fix the SIMM sockets or replace them with improved versions? Will seating the SIMMs with light taps of a small hammer before snapping them into position help?

DISCUSSION -----

This may be related to the interface between the logic board SIMM socket and the SIMM. In some instances, a difference in SIMM circuit board thickness can cause intermittent contact. In others, the SIMM may have minor manufacturing and layout irregularities that are exacerbated by the SIMM socket; other SIMMs may work properly in this situation.

We do not recommend tapping the SIMMs with a hammer--no matter how small a hammer or how light a tap. A focused blow could cause board material fracturing, could dislodge or damage some SIMM components, or could damage or destroy the SIMM socket. The sockets are intended for gentle insertion of the SIMMs.

Here are some suggestions that might help:

- Clean the contacts to eliminate any residual solder flux or other contaminants.

- Compare the suspect SIMMs with others to see if there is any difference in physical dimensions.

Since you indicate that the SIMMs have been reseated many times, the sockets may be in poor condition, and a board replacement may be the only solution at this point.

Article Change History:

09 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7960