



Tech Info Library

TechStep and Third-Party Hard Drives: Error Code 0629

Article Created: 11 December 1992

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I ran Apple's TechStep diagnostic on six Apple 80MB drives, and each drive failed with the same failure code: B1000000:ER:0629, which the TechStep manual does not describe. All six drives pass TechStep's performance diagnostic tests.

Does this error code indicate a problem with the hard drives or the Apple TechStep?

DISCUSSION -----

The 0629 "error" on the self test does not indicate a problem with either the drive or the Apple TechStep.

When the Apple TechStep's self-test mode is started, the SCSI bus is reset. The hard drive's firmware sees that reset and when the self-test is complete, reports back a sense byte and an extended sense byte. In this specific case the sense byte was 06 (unit attention) and the extended sense byte was 29 (bus reset detected).

Hard drives that do this are an exception to the Apple standard. Most Apple drives, when the test is complete, report a zero (0) as the sense byte and extended sense byte. Apple TechStep reports anything that is not a zero as an error condition.

These hard drives are responding exactly as they should, as indicated by their firmware. Even though this is different from what most Apple drives report, these hard drives still meet the general SCSI specifications and should operate properly.

Another drive that we know exhibits the same behavior is the Seagate ST157N.

Copyright 1992, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11070