

Macintosh: Serial Ports Do Not Provide Power For Peripherals

Article Created: 1 July 1985

Article Last Reviewed: 30 June 1992 Article Last Updated: 30 June 1992

TOPIC -----

Is there any way to get power through the serial port to a peripheral?

DISCUSSION -----

Devices (such as modems) may NOT draw power from the Macintosh serial ports. On the Macintosh 128K, 512K and 512K enhanced (which use DB-9 connectors for the modem and printer ports), Pin 6, the +12V pin, is strictly a power-on indicator and may not be used as a power source of any kind.

Macintosh Plus and later computers (which switched to Mini DIN-8 connectors for the serial ports) lack the +5 and +12 Volt signals from the earlier models.

Despite warnings from Apple that the +5 and +12 Volt signals found on the DB-9 serial ports on the 128K and 512K Macintoshes could be removed in the future, some manufacturers designed peripherals that relied on one or both of those signals. These peripherals (e.g. Thunderscan) may not work properly on a Macintosh Plus or later Macintosh due to the removal of the above-mentioned signals. If this is the case, contact the manufacturer of the peripheral for a suggested solution. Some manufacturers offer external power supplies to take the place of the absent signals.

This change also means that a Macintosh application may have to control a peripheral's DTR line.

The serial ports from the Macintosh Plus and later models do not provide power for any peripheral devices. The DTR line (Pin 1) is intended to provide an output handshake signal only, NOT to power external devices.

Any devices connected to the serial ports of the Macintosh Plus or newer models must get their power from an external source, separate from the Macintosh system. Apple does not support devices that receive their power from serial ports.

The solution is to use a separate power source to supply the voltage needed for these modems or peripherals.

Copyright 1988, 1992, Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3202