Global Village Gold II Modem: Unable to Redial (9/96)

Article Created: 23 September 1996

TOPIC ---

My Global Vilalge Teleport Gold II modem (which was included with my Macintosh
Performa computer) connects reliably using PPP, included with the Apple Internet
Connection Kit (AICK), but if I conclude that session by hanging up, and then
attempt to redial, the connection is never established. What is causing this?

DISCUSSION --

According to Global Village Communication (GVC), ALL settings in the Teleport
control panel should be OFF (unchecked). Also, the radio buttons for error
correction should be set to OFF.

The Apple Internet Dialer sets the modem initialization string to AT&F1&K3.
According to Global Village, if you have difficulty using this string, change
this to AT&F1 (which GVC's recommended default setting and is the same as a
generic modem in the AICK Dialer).

You can change to this string either by selecting 'generic' as the Modem Type or
by selecting and editing Add/Modify Modem Type in the Dialer's pop-up dialog
box..

Global Village notes that it may also be necessary to append the string with
&D2, a command which writes out all the buffered data and then hangs up at the
end of the session. In this case, the edited string would be AT&F1&D2.

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

==

This information is from the Apple Technical Information Library.

19960924 07:31:19.00

Tech Info Library Article Number: 20445