



# Tech Info Library

## Apple IIc Upgraded Motherboards: Diagnostics Error (9/95)

Article Created: 20 January 1985

Article Reviewed/Updated: 19 September 1995

TOPIC -----

After an exchange of an upgraded Apple IIc motherboard, running old versions of the Apple IIc diagnostics results in an error condition, most frequently error code number 299.

DISCUSSION -----

The older versions of the diagnostics will not work properly with the upgraded motherboards. Use the most current version of Apple IIc diagnostics (at least Rev. C).

### Article Change History:

19 Sep 1995 - Reformatted to meet current standards.

09 Nov 1988 - Reviewed for technical accuracy.

Support Information Services

Copyright 1988-95, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1675