



Tech Info Library

GS/OS 5.04 Upgrade: Correcting Drive Recognition Problem

Article Created: 13 August 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

I upgraded my Apple IIGS to GS/OS 5.04 on an AppleShare network and it no longer recognizes 5.25 drives.

DISCUSSION -----

When this happens, the 5.25 driver is usually missing from the drivers folder. Run the GS/OS 5.04 Installer again and install the 5.25 drivers. Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8753