



# Tech Info Library

## UPIC: Interfacing the Epson MX-80 Printer

\* Table 2-2, which was to appear on page 10 of the Universal Parallel Interface Card manual, was left out. Refer to the identical table 4-2 on page 19.

\* The Epson printer does not work properly with an Apple II parallel interface cable. Wire the cable as specified in table 2-1 on page 8.

\* The UPIC switch must be set to Auto.

\* The SOS driver configuration block must be set to the values in table 4-2 on page 19 for the Epson MX-80.

Apple Tech Notes

Keywords: <None>

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 620