



Tech Info Library

Hayes InterBridge version 1.06: Improvements

This article last reviewed: 13 August 1987

Version 1.06 of Hayes InterBridge corrects several problems that were reported in version 1.05:

- Down bridge: causes the bridge to become inactive or inaccessible, a large number of buffer allocation errors, or cause the bridge to stop functioning completely.
- Missing bridge: could occur in AppleTalk networks connected with four or more InterBridges. Causes the network manager software to be unable to see the bridge.
- Packet errors: when an InterBridge is combined on an AppleTalk network with a Kinetics Fastpath device, a large number of packet errors occur.
<None>

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2310