



Tech Info Library

Network Software Installer Version 1.4.4 Read Me (7/94)

Article Created: 28 July 1994

TOPIC -----

This article is the Network Software Installer (NSI) Version 1.4.4 Read Me file.

DISCUSSION -----

You can use this Network Software Installer to install the following networking products:

- Update to AppleTalk version 58.1.3
- Network Control Panel version 3.0.2
- AppleTalk Internet Router 2.0 (requires router installation disk)

- EtherTalk version 2.5.6
- Ethernet driver version 1.1.1 for the Apple Ethernet NB Card
- Ethernet driver version 6.0.5 for the Apple EtherTalk NB Card
- Ethernet driver version 1.1.1 for the Apple Ethernet NB Twisted-Pair Card
- Ethernet driver version 1.1.1 for the Apple Ethernet LC Card
- Ethernet driver version 1.1.1 for the Macintosh Quadra 700/900/950/800, Centris 610/650, built-in Ethernet port.
- Ethernet driver version 1.0.1 for the Macintosh Quadra 840AV and Centris 660AV
- Ethernet driver version 1.1.1 for the Apple Ethernet LC Twisted-Pair Card
- Ethernet driver version 1.1.1 for the Apple Ethernet CS Twisted-Pair/Coaxial/AAUI Card

- TokenTalk version 2.5.6
- Token Ring Control Panel version 1.0.1
- Token Ring driver version 2.5.2 for the TokenTalk NB and Token Ring 4/16 Cards

In addition, this Installer installs the following related products:

- A/ROSE 1.2.1

This installer works on either System 6.0.5 or later, or System 7 Macintosh computers.

NOTE:

=====

On Macintosh computers with a 68040 microprocessor (Quadra, Centris, and Performa 470 series), some programs may quit unexpectedly or cause the computer to freeze when you attempt to open them over the network. This problem is fixed by using the Network Launch Fix available from AppleLink or the InterNet (ftp.apple.com).

Restrictions:

=====

This software should not be installed with AppleTalk Internet Router and AppleShare client on a Macintosh with only 1 Megabyte of memory.

If this release of the Network Software Installer is being used in conjunction with an Apple Internet Router v. 3.0 Installer, Router 3.0 must be installed first. This will ensure that the Router installation does not overwrite the newer AppleTalk software contained on NSI 1.4.2.

Release notes for each item follows:

AppleTalk version v58.1.3

=====

The ADSP probe timer won't be reset for every attention packet. This keeps the window sizes updated on each end.

SCC LocalTalk Driver v58.2.2

=====

A fix was made for a slowdown that occurred when using FileShare and ARA Personal server on 680x0 Macintosh computers while communicating with Power Macintosh computers.

Support Information Services

Copyright 1994, Apple Computer, Inc.

Keywords: supt

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15915