



Tech Info Library

Power Macintosh: Teleport Flash Update Fails PCI-Based (5/96)

Article Created: 22 May 1996

TOPIC -----

I tried to run Teleport Flash Update on my 7500 Power Macintosh computer, but it keeps telling me it "won't run on this Macintosh." Why does it run OK on my Quadra 800?

DISCUSSION -----

Description Of Issue

When attempting to run the flash updater for the TelePort Platinum on a Power Macintosh 7200, 7500, 8500, or 9500 series computer an error indicating the "Flasher will not run on this Macintosh" appears. The GlobalFax software version affected is 2.5.3 or higher.

Solution

- This issue has been fixed with firmware version 1.401 now available on all electronic forums.
- Customers must flash the TelePort Platinum modem on all non-PCI-based Macintosh computers.

Affected Products

The Global Village Teleport Platinum is the only modem affected by this issue. No other Global Village modem products (PowerPort 1xx, PowerPort 5xx/Duo, GlobalFax only, OneWorld) are affected.

Only Use Updater On External Modems

The most recent flash update for TelePort modems (1.401) was designed for use ONLY with external TelePort serial modems. Customers who attempt to run the TelePort flash updater 1.401 on their bundled internal TelePort PlatinumV (on Macintosh Performa computers) will get an error message, and the Flasher application will not run at all.

Article Change History:

23 May 1996 - Added info about only using on an external modem.

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960524 08:22:11.00

Tech Info Library Article Number: 19846