



Tech Info Library

AppleLine Not Responding May Be Cable Problem

This article last reviewed: 2 March 1988

If AppleLine is not responding, you may be using the wrong cable.

IF you have set up your Macintosh with a terminal program (such as MacTerminal) and an AppleLine in the following manner:

- AppleLine is connected to the Macintosh by an Apple IIe to ImageWriter II cable and gender changer. Both are connected to a 3174 cluster controller.
- After the AppleLine warms up, the yellow and green lights alternately flash, whether the AppleLine is connected or not.
- MacTerminal has been configured as specified in the manual.

AND, when the AppleLine Supervisor document is opened and you press Shift-Enter and Return, NOTHING HAPPENS -- whether the AppleLine is connected to the cluster controller or not

THEN, your problem is probably a wrong cable.

To connect an AppleLine to a Macintosh Plus, Macintosh SE, or Macintosh II, you must use one of these:

- the A2C0311 590-0331-B Tan
- the A2C0312 590-0555-A Platinum cable

These cables have a DIN 8 at one end and a 25 pin on the other.
<None>

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2729