



Tech Info Library

Power Macintosh: LAT Random Disconnect Problem Fix (5/95)

Article Created: 29 November 1994

Article Reviewed/Updated: 11 May 1995

TOPIC -----

Several people have asked about a problem related to running the LAT Connection Tool on a Power Macintosh and AV computers. The configuration is normally a Power Macintosh running an application that has selected the LAT Connection Tool. The LAT session will disconnect itself randomly.

DISCUSSION -----

The Network Software Installer (NSI) 1.5 will fix this problem, and you should find and install NSI 1.5.

These articles can help you locate NSI 1.5 mentioned here:

- "Where To Find Apple Software Updates" -- Lists online services for free Apple software updates.
- "Obtaining Apple Product Support in the USA" -- Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech Info Library.

The Read Me does not specifically state this fixes the Power Macintosh and LAT problem, however it does.

Article change History:

11 May 1995 - Updated article for NSI 1.5.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: knts,kppc

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16813