



Tech Info Library

Apple IIc: After Upgrade Can't <Open Apple><Ctrl><Reset>

Article Created: 22 April 1986

Article Last Reviewed: 17 July 1992

Article Last Updated:

PROBLEM DESCRIPTION: After an Apple IIc logic PCB has been upgraded, it seems to be unable to perform an Open Apple/Control-Reset.

CAUSE: The board is still able to perform the reset. However the timing in the key strokes is more critical.

CURE: 1. While simultaneously holding the Open Apple and Control keys down, press and release the Reset key.
2. Release the Open Apple and Control keys "after" you have released the Reset key.

If the above cure doesn't fix the problem, search on GTS and the product's name to obtain a general troubleshooting procedure.
Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1883