



Tech Info Library

Macintosh 128K, 512K, Plus: ID = 02 Errors From External Drive

Article Created: 24 October 1985
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Using external drive on left side of Macintosh gets 02 errors.

CAUSE: Drive could be getting RFI interference from power/sweep PCB inside of Mac.

CURE: Use the external drive on the right side of the Mac. If problem still not saved, search on Macintosh General Troubleshooting.
Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1412