



Tech Info Library

Macintosh 128K, 512K, Plus: Distorted Video/Scorched Components

Article Created: 24 October 1985
Article Last Reviewed: 17 July 1992
Article Last Updated:

PROBLEM DESCRIPTION: Left side of Video display stretched with vertical line overlapped. Also often very discolored L2 and/or C2 on power/sweep PCB.

CAUSE: Possible blown flyback circuitry on power/sweep PCB.

CURE: Replace power/sweep PCB. If problem still not found, search on Macintosh General Troubleshooting.
Copyright 1988 Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1413