



Tech Info Library

Macintosh Interrupt

Article Created: 20 May 1986

Article Last Reviewed: 17 July 1992

Article Last Updated:

PROBLEM DESCRIPTION: Customer has purchased the Macintosh 800K Enhancement or Macintosh Plus Upgrade and notices that when pressing "Interurrupt" on the Programers Switch a ">" appears in a dialog box. The prompt and dialog box did not appear on the customers Macintosh 512K before the upgrade occured.

CAUSE: This is not a software or hardware failure, but an added enhancement made to ROM for programing purposes. Pressing the interrupt switch after booting to the "desktop" or executing a program will cause the Macintosh to drop into the Mini-Debugger.

CURE: To exit the Mini-Debugger type "G" and press "RETURN". This will allow the user to resume work without having to reboot the computer.

Copyright 1988, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1960