

ImageWriter II Paper Guide

This article last reviewed: 28 March 1988

PROBLEM DESCRIPTION: The new paper guides seem hard to install when using the old installation procedure documented in the ImageWriter II Technical Procedures manual.

BEFORE YOU START: Familiarize yourself with the ImageWriter II Technical Procedures.

CAUSE: Design changes made to the paper guide require a different method of installation. There are 2 different ImageWriter II paper guides. The NEW paper guide has a reinforcing bar molded to the bottom of the opening that is covered by the "metal foil". The older part does not have this reinforcing bar.

CURE: Remove the print head first before installing the new-style paper guide. See the ImageWriter II Technical Procedures for more information on how to install the paper guide. Then follow the normal paper guide procedure as documented in the ImageWriter II Technical Procedures.

Copyright 1988, Apple Computer, Inc.

Keywords: hts

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2019