

Macintosh LC and IIsi: No Top Lid Screw in US Models

Article Created: 1 May 1991 Article Last Reviewed: 17 July 1992 Article Last Updated:

TOPIC -----

Why does Apple ship the Macintosh IIsi and LC without the screw for the top lid?

DISCUSSION -----

The screw is not included on the US version of the Macintosh IIsi and LC because it is not required in the United States. Copyright 1991, Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7460