



Tech Info Library

Macintosh IIVx: Replacing Logic Board, Buzzing Sound (3/96)

Article Created: 28 March 1996

TOPIC -----

After installing a new logic board in a Macintosh IIVx, the computer no longer makes the usual startup chime, it buzzes for three seconds. Then with power staying on, no video is displayed. What is wrong?

DISCUSSION -----

You need to install VRAM on the logic board. Once this is done the computer should startup in a normal fashion.

Copyright 1996, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960329 07:17:10.00

Tech Info Library Article Number: 19523