



Tech Info Library

SIMMs: Some Are For 68030-Based Systems Only

Article created: 2 March 1989
Article last reviewed: 20 May 1992
Article last updated:

Some of the SIMMs that are used in the Macintosh IIX will not work in other systems (Macintosh II, Macintosh SE, etc). They have "030 ONLY" stamped on the back.

They don't work in other Macintosh systems because the CAS/RAS signals are reversed (timing-related) from previous SIMMs.

This difference is handled in the Macintosh IIX with additional ROM code. Those SIMMs that are marked for "030 ONLY" will work only in the Macintosh IIX (and any future machines that use the 68030 processor).
Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3538