



Tech Info Library

Macintosh Performa: FPU Upgrade Options (7/95)

Article Created: 14 September 1993

Article Reviewed/Updated: 07 July 1995

TOPIC -----

What are the FPU upgrade options for the Performa line of Macintosh computers?

DISCUSSION -----

System	FPU included	FPU upgrade	FPU upgrade method	Notes
Performa 200 (Macintosh Classic II)	No	Yes	3rd party PDS card	
Performa 400 (Macintosh LC II)	No	Yes	3rd party PDS card	
Performa 405	No	Yes	3rd party PDS card	
Performa 410	No	Yes	3rd party PDS card	
Performa 430	No	Yes	3rd party PDS card	
Performa 450 (Macintosh LC III)	No	Yes	Apple Service p/n 922-0107	
Performa 460	No	Yes	Apple Service p/n 922-0107	
Performa 466	No	Yes	Apple Service p/n 922-0107	
Performa 467	No	Yes	Apple Service p/n 922-0107	
Performa 475	No	Yes	Replace 68LC040 w/ 68040	(1)
Performa 476 (Macintosh LC 475; Macintosh Quadra 605)	No	Yes	Replace 68LC040 w/ 68040	(1)
Performa 550 (Macintosh LC 520; Macintosh LC 550)	No	Yes	Apple Service p/n 922-0107	
Performa 560	No	Yes	Apple Service p/n 922-0107	
Performa 575 (Macintosh LC 575)	No	Yes	Replace 68LC040 w/ 68040	(1)
Performa 577	No	Yes	Replace 68LC040 w/ 68040	(1)
Performa 578	No	Yes	Replace 68LC040 w/ 68040	(1)
Performa 600 (Macintosh IIVx)	No	Yes	Apple Service p/n 922-0107	
Performa 63x (Macintosh LC 630; Macintosh Quadra 630)	No	Yes	Replace 68LC040 w/ 68040	(1)

Notes:

(1) - Apple does not recommend or support replacing the CPU chip.

Article Change History:

07 Jul 1995 - Added comparable computers information

20 Mar 1995 - Updated part number for Apple FPU.

29 Jul 1994 - Added Performa 63x.

Support Information Services

Copyright 1993-95, Apple Computer, Inc.

Keywords: review

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13226