

Macintosh: Error 51 Unserviceable Slot Interrupt

That error is: "Unserviceable slot interrupt."

In general, this type of error is caused by a corrupt operating system, Ethernet driver, or a software incompatibility between any of these and INITs or CDEVs. Try trashing and re-installing the operating system and Ethernet drivers. If that fails to solve the problem, try removing all unnecessary third-party INITs and CDEVs. If the system works at this point, re-install them one at a time and restart each time to find the culprit. Copyright 1991, Apple Computer, Inc.

Keywords: <None>

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8101