



Tech Info Library

Differences Between AppleTalk v58.1.5 and v58.1.6 (1/96)

Article Created: 17 October 1995

Article Reviewed/Updated: 12 January 1996

TOPIC -----

What are the changes made from AppleTalk v58.1.5, distributed on the Network Software Installer (NSI) 1.5.1, to AppleTalk v58.1.6, shipped on the PowerBook 5300 series computers?

DISCUSSION -----

The change to AppleTalk v58.1.6 was needed to implement built-in infrared technology (IRTalk). If the version number for AppleTalk had not been revised with the PowerBook 5300 Series computers, then running NSI 1.5.1 would overwrite the IRTalk changes. So by changing AppleTalk to v58.1.6, even if a user does run NSI 1.5.1, the AppleTalk resources will not be written over because the version pre-installed on the PowerBook is newer than the one on the NSI 1.5.1 disk.

Article Change History:

12 Jan 1996 - Revised for clarity.

Support Information Services

Copyright 1995-96, Apple Computer, Inc.

Keywords: knts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18757