



# Tech Info Library

## 32-Bit Mode: Use SuperClock 3.9.1 for II, IIx, IICx, SE/30 3/93

Article Created: 8 October 1991

### Article Change History

-----  
08/21/92 - RETITLED

- For clarity; edited.

03/02/93 - REVISED

- To add 32-Bit System Enabler information.

### TOPIC -----

The Macintosh II, IIx, IICx, and SE/30 crash on restart with SuperClock installed and set to 32-bit mode.

### DISCUSSION -----

This problem with SuperClock occurs on these Macintosh computers only when they are used in 32-bit mode, such as with A/UX, the 32-Bit System Enabler, or MODE32.

Upgrade to SuperClock 3.9.1 or later, the version that fixes the crash problem in 32-bit mode.

Copyright 1991, 1992, 1993, Apple Computer, Inc.

Keywords: sys7

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8935