

## Tech Info Library

## MODE32 v.7.5: Incompatible With Launcher (5/95)

Article Created: 19 October 1994 Article Reviewed/Updated: 25 May 1995
TOPIC
The Launcher does not work with Connectix's Mode32 v7.5 on the following CPUs:
<ul> <li>Macintosh II</li> <li>Macintosh IIx</li> <li>Macintosh IIcx</li> <li>Macintosh SE/30</li> </ul>
When the Launcher is opened, the window is empty. Turning off Mode32 lets the Launcher show all of its items.
DISCUSSION
This problem has be resolved by the System 7.5 Update 1.0.
These articles can help you locate the software update mentioned here:
• Where To Find Apple Software Updates Lists online services for "free" Apple software updates.
• Obtaining Apple Product Support in the USA Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library.
Article Change History: 25 May 1995 - Added information about System 7.5 Update 1.0. 14 Feb 1995 - Updated keyword; reviewed for technical accuracy. 02 Feb 1995 - Removed invalid workaround information.
Support Information Services Copyright 1994-95, Apple Computer, Inc.
Keywords: sys75,ksts

\_\_\_\_\_\_

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16561