



Tech Info Library

System 7.5: Menu Bar Clock Anomaly After Installation (2/95)

Article Created: 10 January 1995

Article Reviewed/Updated: 16 February 1995

TOPIC -----

When System 7.5 was installed over the original System 7.1 on my PowerBook 180, I got some strange behavior from the clock. That is, the time and date continuously change with a change delay of about half a second.

DISCUSSION -----

We are aware of some Macintosh computers exhibiting this type of problem when System 7.5 is installed on a Macintosh with the SuperClock control panel previously installed.

We recommend disabling SuperClock, or any extension that puts the time/date in the menu bar. The Date & Time control panel offers this type of functionality. As an alternative, you can turn off the Menubar Clock in the Date & Time control panel.

Article Change History:

16 Feb 1995 - Changed keyword and reviewed technical accuracy.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: sys75

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16982