



# Tech Info Library

## Macintosh IIci: System Update and Daystar Digital Compat. (3/95)

Article Created: 21 March 1995

TOPIC -----

Are there any known issues with the DayStar Digital Turbo 601 and the System 7.5 Update 1.0?

DISCUSSION -----

A Macintosh IIci with the DayStar Digital Turbo 601 will not boot with the System 7.5 Update 1.0 installed if you are using a version earlier than 1.1 of the "Turbo 601" control panel.

Please contact DayStar Digital for an update.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number. You can also search the Tech Info Library using the vendors name as a search string.

Support Information Services  
Copyright 1995, Apple Computer, Inc.

Keywords: sys75

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17393