



Tech Info Library

System 7 Pro: Read Me Incorrect About Apple IIe Card SW (10/93)

Article Created: 20 October 1993

TOPIC -----

The information about how to obtain Apple IIe Card Software in the Read Me file for System 7 Pro is incorrect. This article explains the best ways to obtain this software.

DISCUSSION -----

The Read Me file that is installed when updating to System 7 Pro reads as follows:

"APPLE IIe CARD SOFTWARE FOR THE MACINTOSH LC II

To use the Apple IIe Card with System 7 Pro on a Macintosh LC II, you need version 2.2 of Apple IIe Card Software. You should upgrade to version 2.2 only if you are using your LC II with System 7 Pro. Apple IIe Card Software 2.2 may also be used with the original Macintosh LC, but it is not required.

You can obtain the upgrade package from an authorized Apple Reseller. In the United States, you can call the Apple Customer Assistance Center at 1-800-776-2333 to request Apple IIe Card Software version 2.2. The new software is also available on AppleLink (AppleLink path: Apple Products: Apple II: Apple II Product Information: Apple IIe Card)."

These instructions aren't correct.

Contact an Apple Reseller to purchase the IIe software update, or download it from AppleLink. You can call the Apple Referral Center at 1-800-538-9696 to locate a reseller near you to purchase Apple part M1222LL/C, Apple IIe card Software Update.

Apple IIe Card (2.2.1) software is available for customers on AppleLink using the following path:

- Software Sampler
- Apple SW Updates
- Macintosh
- Peripheral Software
- Apple IIe Card (2.2.1)

Copyright 1993, Apple Computer, Inc.

Keywords: SUPT

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13749