



Tech Info Library

Drive Setup 1.0.3: Read Me (12/95)

Article Created: 06 December 1995

Article Reviewed/Updated: 11 December 1995

TOPIC -----

This is the Read Me file for Drive Setup 1.0.

DISCUSSION -----

What's New in Drive Setup 1.0.3?

- No changes to SCSI driver. This is the same SCSI driver that is included with Drive Setup 1.0.2.
- Installs updated IDE driver (ATA v1.12) for systems that were previously supported by previous versions of Drive Setup.
- Some Apple IDE hard drives require extra time to flush its caches at shut down and restart. This new IDE driver insures that the drive's caches are properly flushed.
- Corrects an issue with the PowerBook 190, 2300 and 5300 series of computers where, in some cases, the system will freeze after wake up.

Drive Setup 1.0.3 requires System Software 7.5 (or later) and is only supported for use with the following systems:

- Power Macintosh systems (including PowerPC-based Performa systems)
- Macintosh 580- and 630-series systems
- PowerBook 190, 2300, and 5300

Drive Setup does not currently support the Macintosh Processor Upgrade. If the upgrade is installed in a Macintosh 580- or 630-series system, use the "601 Processor Upgrade" control panel to turn the card off before using Drive Setup.

Article Change History:

11 Dec 1995 - Updated information.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 19028