



# Tech Info Library

## Drive Setup: What's New in v1.0.5 & v1.1? (6/96)

Article Created: 05 June 1996

TOPIC -----

I noticed that the Power Macintosh 5260/100 includes version 1.0.5 of Drive Setup, and the Power Macintosh 5400/120 includes version 1.1. What is different in these versions from version 1.0.4, which was included with System 7.5 Update 2.0?

DISCUSSION -----

Following are the changes made to versions from Drive Setup version 1.0.4 to 1.0.5 and 1.1:

1.0.4 -> 1.0.5

- Drive Setup 1.0.5 waits 3 seconds between calls to the Disk Init Package ensuring that volume creation dates are different. This prevents a problem with custom icons not appearing correctly on drives with multiple partitions.

1.0.5 -> 1.1

- Provides DMA support for ATA based machines.
- Fixed a problem where an ATA device's capacity was not correctly recognized.

Copyright 1996, Apple Computer, Inc.

Keywords: supt

=====  
This information is from the Apple Technical Information Library.

19960606 07:04:28.00

Tech Info Library Article Number: 19967