



Tech Info Library

AppleCD: When Replacing Mechanism, Install New Software (3/93)

Article Created: 18 March 1993

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I have a Macintosh IIvx that required a CD-ROM drive replacement. When I installed the new Service Module, the drive would not mount. I reinstalled CD Software version 4.01, but the problem still occurred.

DISCUSSION -----

In December 1992, Apple released version 4.0.2 of the Macintosh CD-ROM Setup software, which resolves anomalies with the drive and certain Macintosh computers.

In all cases we have heard of, the computer systems that would not mount the CD-ROM drive were not running version 4.0.2 as required. Once the CD-ROM Setup Software version 4.0.2 was installed, all systems worked fine.

When a Service Provider replaces any internal or external CD-ROM drive, make sure the system is under 4.0.2 and the customer is provided with this latest version of the software. Using this software will prevent the customer from experiencing problems that occurred with earlier software versions. Advise the customer that this software must be installed using the Apple Installer program.

Download Macintosh CD-ROM Setup Software 4.0.2 from the AppleLink path:

- Software Sampler icon
- Apple SW Updates bulletin board
- Macintosh folder
 - Peripheral Software folder
 - Macintosh CD-ROM Setup 4.0.2

Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11799