



Tech Info Library

ImageWriter II: Hiss May Be Slight Electrical Short (11/94)

Article Created: 14 May 1991

Article Reviewed/Updated: 10 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

The color ribbon was not working properly on my ImageWriter II so I replaced the Drive PCB which fixed that problem. However, it now has an electronic hiss coming from the Drive PCB area. This unit also has an AppleTalk option card installed.

What could be causing the problem (bad printhead, motor assembly for the color ribbon, main logic board)?

DISCUSSION -----

The noise could be generated by a component on the Drive PCB with a mild short. The unit may have problems, especially if it is moved causing the short to increase. The only solution is to replace the Drive PCB.

Article Change History:

10 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8235