



# Tech Info Library

## ImageWriter II: Workaround for Unseating Option Card (9/94)

Article Created: 1 May 1992

Article Reviewed/Updated: 30 September 1994

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

Periodically, a customer brings in an ImageWriter II because the Option Card has become unseated. Is there a different standoff available that will eliminate this problem?

DISCUSSION -----

We are aware of the problem you describe. We tried a number of different size standoffs with no consistent positive results. The problem seems to be related to the flap tension.

The best workaround we've found is to clip part of the tension flap on the existing standoff. At this time, none of the ImageWriter II printers modified with this procedure has been returned.

We have included a graphic, in PICT format, that shows a modified standoff.

The binary attachment (ex. utility/application/file/extension) mentioned in this article is enclosed only in the on-line AppleLink version of the article. If you are accessing this article outside of AppleLink, and you want to download the attachment:

- 1) In AppleLink, open the Tech Info Library.
- 2) Search for this article.
- 3) Open the article and click "Download".

Article Change History:

30 Sep 1994 - Reviewed for technical accuracy.

05 Apr 1993 - Updated to include a graphic showing a modified standoff

Support Information Services

Copyright 1992 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10172