



Tech Info Library

LW IINTX, IIf, IIg: Correction to Peripheral Interface Guide

Article Created: 11 May 1992

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

This is a notice about incorrect information for the LaserWriter IINTX, LaserWriter IIf, and LaserWriter IIg in the Peripheral Interface Guide.

DISCUSSION -----

Page 5, Peripherals, of the Peripheral Interface Guide, incorrectly states that 5 volts exists on pin 38 of the LaserWriter IINTX and LaserWriter IIf and IIg. The 5 volts on pin 38 exists only on the Personal LaserWriter SC. Copyright 1992 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10203