



Tech Info Library

Macintosh IICx: No Cap. C17 on Rev. B and Later Boards (11/94)

Article Created: 2 August 1991

Article Reviewed/Updated: 09 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

A dealer repairing a Macintosh IICx logic board noticed that, although "C17" is marked on the underside of the board, there was no such capacitor on the logic board.

Should this logic board have a capacitor at C17?

DISCUSSION -----

Capacitor C17 was removed from all revision B and later logic boards. It also may have been removed from earlier revision boards; for example, before the logic board completed production validation testing. In any case, there is no problem using the board without the capacitor at C17.

Article Change History:

09 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7961