



# Tech Info Library

## Macintosh: Direction of DRAM SIMM Chips Can Vary (11/94)

Article Created: 14 June 1991

Article Reviewed/Updated: 10 November 1994

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

I need to replace the SIMMs in Bank A of my Macintosh IIci. I notice that these SIMMs have their DRAM chips mounted with Pin 1 up instead of down toward the edge connector. The Module Identification Manual shows the chips mounted with Pin 1 down. Which way is correct?

DISCUSSION -----

The chips on the SIMM can be mounted in either direction depending on the manufacturer of the SIMM. Apple sells some SIMMs with Pin 1 on top and other SIMMs with Pin 1 on the bottom.

Article Change History:

10 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94 Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8504