



# Tech Info Library

## Macintosh SE: Some Work Only In 1MB and 4MB RAM Configurations

Article Created: 5 March 1993

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

### TOPIC -----

There are some Macintosh SE systems that only work in 1MB and 4MB RAM configurations. If you attempt a 2MB or 2.5MB configuration, with jumpers in any setting and with SIMMs in either position, the system crashes, gives Sad Mac tones, produces a checkerboard, and so on.

### DISCUSSION -----

This problem is related to an earlier problem of the Macintosh SE main logic boards (661-0536), which required reverse jumpering to work with 2MB or 2.5MB configurations. All service sites have been notified of this problem and have been asked to take corrective action in their processes. Dealerships can't rework these boards. You must send the board to Apple for exchange.

Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11742