



Tech Info Library

MPEG Media System: Distorted Audio Caused by Card (11/96)

Article Created: 27 November 1996

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

After installing the Apple MPEG Media System card (service part number 661-0995), the audio became distorted. Why?

DISCUSSION -----

You need to replace the MPEG Media System card. The newer revision of the MPEG Media System card corrected this issued. You can tell the difference between the two cards by looking at the jumpers on the card. The newer revision has a jumper installed from U5 Pin 2 to D1 Pin 1 on the card.

Copyright 1996, Apple Computer, Inc.

Keywords: hts

=====
This information is from the Apple Technical Information Library.

19961127 14:16:41.00

Tech Info Library Article Number: 20683