



Tech Info Library

Power Macintosh: 8100/80 Will Not Boot From CD (6/94)

Article Created: 01 June 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

When using a Power Macintosh 8100/80 with 264 megabytes of RAM, the system will not boot off the included "Power Macintosh CD". The machine will display a flashing "?". Is there a problem with the RAM?

DISCUSSION -----

This problem existed with the CD Boot driver present on the "Power Macintosh CD". This has been corrected in version 2.0 of the CD which began shipping with Power Macintosh systems during the last week of May 1994.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: kppc

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15506