



Tech Info Library

PowerBook 500 Series: Difficulty Ejecting Diskettes (2/95)

Article Created: 28 June 1994

Article Reviewed/Updated: 24 February 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

My PowerBook 500 series computer sometimes has difficulty ejecting diskettes. Is this a known issue?

DISCUSSION -----

Some PowerBook 500 series computers may have difficulty ejecting diskettes. This cause involves slightly out of spec floppy disk drives installed in computers between the following serial number ranges:

FC410 through FC414
CK412 through CK414

Service drive mechanisms are not affected by this issue, order part number 661-0061 to resolve the problem under warranty.

Article Change History:
24 Feb 1995 - Corrected serial number range.

Support Information Services
Copyright 1994-95, Apple Computer, Inc

Keywords: kpbook

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15717