



Tech Info Library

StyleWriter II Driver (1.2): Bug w/Adobe Type Align (9/93)

Article Created: 20 September 1993

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I have a Performa 600, System 7.1P, a StyleWriter II, and Adobe TypeAlign. If a curve is printed, an ink blot occurs. Is there an update to the StyleWriter II driver that resolves this issue?

DISCUSSION -----

There is in fact a new StyleWriter driver (v1.2) that has been released, but unfortunately Apple has verified that the problem still occurs. It is unclear at this time whether the problem lies in the driver, or with Adobe TypeAlign. We are reporting this as a bug to engineering so that they can investigate this further. In the interim, we are not aware of a workaround other than to avoid printing to a StyleWriter II (as well as a Personal LaserWriter 300 and LaserWriter Select 300 - see below).

NOTE: There are a couple of things to be aware of. The first is that this problem also occurs on the Personal LaserWriter 300 and LaserWriter Select 300 printers since they are based on the same source code as the StyleWriter II. The second is that the StyleWriter II is NOT listed as a supported printer on the outside of the box of Adobe TypeAlign, we have version 1.0.5.

Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13345