



# Tech Info Library

## Macintosh: Pioneer CD Requires Lower SCSI ID (3/95)

Article Created: 1 March 1995

TOPIC -----

I installed a Pioneer DRM-600 CD changer with driver v3.0 on my Macintosh. After installing the Pioneer driver the internal CD drive can no longer be seen by the system.

DISCUSSION -----

According to Pioneer you need the 3.0 version of the driver for System 7.5 compatibility and replaces the Apple CD-ROM driver.

Pioneer has also discovered that their DRM-600 drive needs to have a lower SCSI ID than the SCSI ID of the internal CD-ROM from Apple. Apparently, this contradicts the recommendations in their read me.

If your internal CD-ROM drive is set to SCSI ID 3 (the ID set by Apple at the factory), set the Pioneer DRM-600 drive to SCSI ID 1 or 2.

For additional information on this problem, contact Pioneer.

Support Information Services  
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17294