



# Tech Info Library

## Apple Telecom 2.2 Fixes AudioTuneUp In Apple Telecom 2.1 (8/95)

Article Created: 17 August 1995

Article Reviewed/Updated: 31 August 1995

TOPIC -----

This article describes an issue with Internationally localized Apple Telecom 2.1 and AudioTuneUp which is installed on PCI-based Power Macintosh computers.

DISCUSSION -----

Below are the symptoms of a problem in AudioTuneUp installed by Apple Telecom 2.1, that were fixed by AudioTuneUp 1.0.1 in Apple Telecom 2.2. Anyone who has installed a localized version of Apple Telecom 2.1 should replace AudioTuneUp with version 1.0.1 which is included as part of Apple Telecom 2.2

The Sound control panel functions do not work as follows:

- Alert sounds:
  - The add button does not function.
  - A beep is not output when the alert volume slider is dragged up and down.
- Sound In: There is no sound source.
- Sound Out: Rate, Size, and Use are dimmed.
- Volumes:
  - The headphone volume scales disappear.
  - Mute doesn't work.
  - The volume's slider is fixed at MAX.

Article Change History:

31 Aug 1995 - Grammar correction.

21 Aug 1995 - Made minor correction.

Support Information Services

Copyright 1995, Apple Computer, Inc.

Keywords: knts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18401